



3671 N Dixie Hwy, Deerfield Beach, FL 33064  
 954-785-4820 rivamotorsports.com

# Repair Order

**Due: \$3,670.70**

Doc Number: 134645

Service Writer: Adam Nortman

Date Printed: 11/20/2025

Date Promised: 11/19/2025

**CARLOS**

**XXXXXXXX**

**POMPANO BEACH, FL 33064**

## Customer Information

Home Phone: 954-XXX-XXXX

Fold Here

## Summary

Approve	Decline	Unit	Job	Job Total
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2023 YAMAHA VX1050A-Y	USED UNIT CHECK OVER	\$3,280.56

**Job Subtotal: \$3,280.56**

**Misc: \$150.00**

**Job Parts Subtotal: \$1,845.56**

**Job Labor Subtotal: \$1,435.00**

**STATE SALES TAX - 6.00%: \$205.83**

**COUNTY SALES TAX - 1.00%: \$34.31**

**Total: \$3,670.70**

**Less Deposits: \$0.00**

**Total Due: \$3,670.70**

30 DAY WARRANTY ONLY ON WORK PERFORMED. WARRANTY DOES NOT APPLY TO REPAIRS ON VEHICLES USED FOR RENTING OR RACING. STORAGE FEES START 5 DAYS AFTER COMPLETION OF WORK AT A RATE OF \$50.00 PER DAY. RIVA HAS A SHOP LABOR RATE OF \$189/ HOUR FOR MOTORCYCLES/ATVS AND \$205/HOUR ON BOATS AND PWC. FL REG# MV722 SHOULD YOU DECLINE WORK TO BE PERFORMED AFTER DIAGNOSIS, YOUR UNIT MAY HAVE BEEN DISASSEMBLED DURING THIS DIAGNOSTIC PROCESS AND THERE MAY BE AN ADDITIONAL CHARGE TO RE-ASSEMBLE IT. DUE TO SPACE LIMITATIONS, RIVA DOES NOT TAKE IN PWC TRAILERS.

Received by: \_\_\_\_\_ Vin# \_\_\_\_\_

Date / Time: \_\_\_\_\_

Signature: \_\_\_\_\_

# Detail

**Unit**    2023 YAMAHA VX1050A-Y VX LIMITED-  
 AZURE BLUE/WHITE  
 VIN/Serial No:YAMA1113J223

**Color:**  
  
**Plate:**

**Keyboard:**  
  
**Odom/Hrs In:62.7    Out:62.7**

**USED UNIT CHECK OVER**

**Description:**UNIT HAS NO ELECTRICAL POWER AT TIME OF DROPOFF

**Recommend:**UPON INSPECTION TECH FOUND BATTERY IS BAD AND WILL NEED TO BE REPLACED. TECH FOUND EVIDENCE OF A FIRE EXTINGUISHER BEING DISCHARGED IN THE BILGE, SEVERAL MELTED WIRES AND ELECTRICAL CONNECTORS IN THE ENGINE COMPARTMENT. TECH SAYS IT APPEARS MOTOR WAS ON FIRE AT SOME POINT. TECH NOTED WIRING HAS BEEN REPAIRED WITH ELECTRICAL TAPE AND SAYS HARNESS AND HANDLEBAR SWITCHES WILL NEED TO BE REPLACED. UNIT HAS AFTERMARKET WIRING POORLY INSTALLED INTO MAIN HARNESS, POSSIBLY FOR A GPS UNIT, AUDIO SYSTEM DOES NOT WORK, UNIT HAS COMPRESSION OF 190/175/175.

**Parts**

Part #	Qty	Description	Price	Discount	Total
6JS-8259L-01-00	1.00	WIRE HARNESS ASSY 1	\$1,268.89	\$0.00	\$1,268.89
F4P-8259E-12-00	1.00	SWITCH ASSY.	\$389.89	\$0.00	\$389.89
F4P-81860-01-00	1.00	SWITCH ASSY.	\$158.89	\$0.00	\$158.89
ACC-RNGFR-PL-12	1.00	RINGFREE PLUS 12OZ 1	\$27.89	\$0.00	\$27.89
<b>Parts Subtotal</b>					<b>\$1,845.56</b>

**Labor**

Description	Total
UNIT CHECK OVER	\$205.00
REPLACE WIRING HARNESS	\$615.00
REPLACE LEFT SWITCH ASSY	\$205.00
REPLACE RIGHT SWITCH ASSY	\$205.00
WATER TEST	\$205.00
<b>Labor Subtotal</b>	<b>\$1,435.00</b>
<b>Job Subtotal</b>	<b>\$3,280.56</b>
Approve: <input checked="" type="checkbox"/>	Decline: <input type="checkbox"/>

<b>All Jobs Subtotal:</b>	<b>\$3,280.56</b>
<b>Shop Supplies:</b>	<b>\$150.00</b>
<b>STATE SALES TAX - 6.00%:</b>	<b>\$205.83</b>
<b>COUNTY SALES TAX - 1.00%:</b>	<b>\$34.31</b>
<b>Total:</b>	<b>\$3,670.70</b>
<b>Less Deposits:</b>	<b>\$0.00</b>
<b>Total Due:</b>	<b>\$3,670.70</b>